on the instrument panel cluster, along with Diagnostic Trouble Codes (DTC) P0507 stored in the Powertrain Control Module (PCM). In some cases, higher than expected engine idle Revolutions Per Minute (RPM)s may be experienced. The torn/split rubber membrane has been found to be vulnerable to degradation from higher than anticipated blow-by gas condensate acidity levels which occur when operating on fuels blended with ethanol. PCV R/I

RTSQTYFP-NUMBER 1 LR166809 1 LRN0002LABEL	SERVICE KIT - P	TOTAL - PARTS	WARRANT WARRANT 0.00
B# 5 TOTALS			
DB# 6 CHARGES	JOB# 5 JOURNAL PREFIX LRO	CS JOB# 5 TOTAL	0.00
# 6 O4LRZ3PPOS BG 3P OIL FILT CH	MANCE OIL AND FILTER CHANGE	.034289	252.00
1 6577	FILTER - ENGINE CASTROL EDGE PR PERF OIL SERVIC	30.99 18.99 59.95 TOTAL - PARTS	
OB# 6 TOTALS		LABOR PARTS	252.00 280.84
JOB# 7 CHARGES	JOB# 6 JOURNAL PREFIX LRCS	JOB# 6 TOTAL	532.84
ABOR # 7 04LRZEK BG ETHYNOL KIT TECH(S):01034289 PERFORM BG ETHYNOL KIT PERFORMED BG ETHYNOL KIT		42.00	
PARTSQTYFP-NUMBER 1 2913	DESCRIPTIONETHYNOL KIT	UNIT PRICE- 39,95	39.95
PAGE 2 OF 3 CUSTOME	ER COPY [CONTIN	IUED ON NEXT PAGE). 11	Lilam