

EXHAUST TAILPIPE CORROSION – 5.0L AJ133-8 CYLINDER ONLY

Defender

- 20–24MY Defender

Customer Voice:

- JLR Retailers have reported visible corrosion around the outlet of the exhaust tailpipe prior to PDI

Technical Description:

- The concern is currently under investigation.

Status:

- Please find attached an example image showing light corrosion.
- Where mild corrosion is visible on the exhaust tail pipe, clear away the corrosion using a non metallic scouring pad or suitable mild cutting paste.

Refer to SSM 76106

