

<b>Reference</b>	SSM75349
<b>Models</b>	Defender / L663
<b>Title</b>	L663 21MY Stop / start functionality Inoperative
<b>Category</b>	Driveability
<b>Last modified</b>	12-May-2021 00:00:00
<b>Symptom</b>	603300 No Start

**Content**            **Engine variant-** AJ20 P6

**Issue-** Customer reports stop start inoperative on 21Y L663 AJ20P6

**Cause –** PCM Calibration error

**Action –**

**This procedure requires a minimum of Pathfinder 326 installed or later.**

- 1. Connect the JLR approved battery support unit**
- 2. Connect the JLR approved diagnostic equipment to the vehicle and begin a new session.**
- 3. The JLR approved diagnostic tool will read the correct VIN for the current vehicle and automatically take the vehicle out of 'Transportation mode' if required.**
- 4. Follow the JLR approved diagnostic equipment prompts**
  - 1. Select 'ECU Diagnostics'**
  - 2. Select 'Powertrain Control Module [PCM]'**
  - 3. Select 'Update ECU'**
  - 4. Follow all on-screen instructions to complete this task**
- 5. When the task is completed, exit the session**
- 6. Disconnect the JLR approved diagnostic equipment and the JLR approved battery support unit**

dWJvbmZbnRiOziwMjEIMDUIMThUMTI6NTg6NDUuMz3Wjs0Ny4yOC42Ni40MTY1QUxFOFdFVTRMMjAxMjQyNw==