

## Vehicle Fault Diagnostic Report

Brand : LANDROVER\_DC

Model :

Year :

VIN Code : SALAG25406A359335


ODO :

Vehicle Soft Version : V33.40

Diagnostic APP Version iOS 1.4.0

Diagnostic Date : 2019-10-09 21:29:56

Diagnostic Path : Discovery 3 > Normal Aspirated Petrol V8 > Health Report



Diagnostic Result :

Fault	(34)	
TCM (Transmission control module)	1	Abnormal
U0155-87	Lost communication with instrument cluster control module	Permanent
IPC (Instrument cluster control module)	5	Abnormal
U0102-87	Lost communication with transfer case control module	Intermittent
U0132-87	Lost communication with ride level control module	Intermittent
U0159-87	Lost communication with parking assist control module	Intermittent
U0184-87	Lost communication with audio unit	Intermittent
B1A87-68	Battery disconnection/ electronic control unit reset	Historic
RLM (Ride level control module)	3	Abnormal
C1A13-64	Pressure does not decrease when venting gallery.	Intermittent
C1131-92	Air supply.	Intermittent
C1A20-64	Pressure increases too slow when filling reservoir.	Permanent
ATCM (All terrain control module)	1	Abnormal
U0421-94	Invalid data received from ride level control module	Pending
TCCM (Transfer case control module)	1	Abnormal
P0562-00	System voltage low	Intermittent
VDM (Vehicle dynamics control module)	1	Abnormal
U0132-87	Lost communication with ride level control module	Intermittent
ACM (Audio front control module)	1	Abnormal
U1A03-62	Vehicle configuration parameter	Intermittent
BCM (Body control module)	9	Abnormal
B1A00-16	Control module	Intermittent
B1A99-4C	Power on reset	Pending
B1B02-28	Low frequency coil	Permanent
B1BA0-66	Suspicious starting activity.	Permanent
B1C16-3A	Passenger's left/right mirror motor feedback circuit	Permanent
B1C57-14	Unused relay drive.	Intermittent
B1D12-15	Volumetric alarm power circuit	Intermittent
U0155-87	Lost communication with instrument cluster control module	Intermittent
U2001-68	Reduced system function	Intermittent
FEM (Front entertainment control module)	1	Abnormal
U1A01-31	Communication link	Intermittent
HVAC (Heating ventilation and air conditioning control module)	7	Abnormal
B1B74-00	Front foot-defrost mode stepper actuator	Permanent
B1B75-00	Front foot-face mode stepper actuator	Permanent
B1B76-00	Front left air blend stepper actuator	Permanent
B1B77-00	Front right air blend stepper actuator	Permanent
B1B78-84	System pressure	Intermittent
B1B82-00	Rear air distribution	Permanent