

2020.0 DEFENDER (LE), 415-01

ICCM (INFOTAINMENT COMPUTE CONTROL MODULE) - ASSEMBLY PART NUMBER: L8B2-19L310-JL,L8B2-19L310-SL,L8B2-19L310-TL (G2748986)

PIVI IP26

Software Release Date: 2020-10-05

SOFTWARE RELEASE NOTES

NOTE

THE SOFTWARE UPDATE FOR THIS RELEASE NOTE IS AVAILABLE ON THE FOLLOWING SYSTEMS -

- Software Over The Air (SOTA)
- Pathfinder

INTRODUCTION

This Document contains the following information:

Issues fixed in this release

- [Bluetooth® audio](#)
- [Media Player](#)
- [Navigation](#)
- [SDARS](#)
- [Settings](#)
- [Speech](#)
- [System](#)
- [Tow Assist](#)

NEW FEATURES INCLUDED IN THIS RELEASE

THE SOFTWARE RELEASE DOES NOT CONTAIN ANY NEW FEATURES.

ISSUES FIXED IN THIS RELEASE

BLUETOOTH® AUDIO

- An issue with last played over Bluetooth® not being available after ignition cycle has been fixed.

MEDIA PLAYER

- An issue with the media feature not launching has been fixed.
- An issue with a 5 second delay after launching USB media has been fixed.

NAVIGATION

- An issue with extra features view not being shown after the pressing the home button from the navigation view has been fixed.
- An issue with the map theme defaulting back to light mode after the theme is set to dark mode has been fixed.
- An issue with the system not returning to navigation search feedback screen when exiting the reverse camera view has been fixed.

SDARS

- An issue with a 5 second delay after launching SDARS search page has been fixed.

SETTINGS

- The system will no longer switch between UK and US English when not requested.

SPEECH

- An issue with the speech pop having a long delay after launching has been fixed.

SYSTEM

- The 4x4i screen will now always launch.

TOW ASSIST

- An issue when selecting Tow trailer it is not launching general profile has been fixed.
-

KNOWN ISSUES IN THIS RELEASE

THERE ARE NO KNOWN ISSUES IN THIS SOFTWARE RELEASE.