

---

<b>Reference</b>	SSM75427
<b>Models</b>	Defender / L663 Discovery / L462 Discovery Sport / L550 New Range Rover Evoque / L551 Range Rover Velar / L560
<b>Title</b>	Wireless Device Charger Module (WDCM) Not Charging iPhone 12
<b>Category</b>	Electrical
<b>Last modified</b>	03-Jun-2021 00:00:00
<b>Symptom</b>	207000 Entertainment Systems

---

**Content**      **Issue:**  
JLR is investigating customers reporting iPhone 12 with MagSafe not charging when using the Wireless Device Charger feature.

**Cause:**  
Wireless Device Charger Module (WDCM) doesn't support with new iPhone 12 MagSafe feature.

**Action:**  
**This procedure requires a minimum of Pathfinder (325) loaded or later.**

- Connect the JLR approved battery support unit.
- Connect the JLR approved diagnostic equipment to the vehicle and begin a new session.
- Follow the JLR approved diagnostic equipment prompts.
- Select 'ECU Diagnostics'.
- Select 'WDCM'
- Select 'Update ECU'.
- Follow all on-screen instructions to complete the task.
- When all of the tasks are complete, exit the session.
- Disconnect the JLR approved diagnostic equipment and the JLR approved battery support unit.
- Confirm the Wireless Device Charger Module (WDCM) charges the iPhone 12

Thank you in advance for your assistance with this matter.