

ENGINE MANAGEMENT SYSTEM - V8



P Code	J2012 Description	Land Rover Description
P0308	Cylinder 8 misfire detected	Injector 8 excess emissions/catalyst damaging level of misfire
P0171	System too lean (bank 1)	Multiplication injector adaptive fuelling - lean limit exceeded LH bank
P0172	System too rich (bank 1)	Multiplication injector adaptive fuelling - rich limit exceeded LH bank
P0174	System too lean (bank 2)	Multiplication injector adaptive fuelling - lean limit exceeded RH bank
P0175	System too rich (bank 2)	Multiplication injector adaptive fuelling - rich limit exceeded RH bank
P1171	System too lean (bank 1)	Additive injector adaptive fuelling - lean limit exceeded LH bank
P1172	System too rich (bank1)	Additive injector adaptive fuelling - rich limit exceeded LH bank
P1174	System too lean (bank 2)	Additive injector adaptive fuelling - lean limit exceeded RH bank
P1175	System too rich (bank 2)	Additive injector adaptive fuelling - rich limit exceeded RH bank
P0300	Random/multiple cylinder excess emissions detected	Excess emissions detected on more than one cylinder
P1300	Random/multiple cylinder misfire detected	Catalyst damaging level of misfire on more than one cylinder
P1319		Misfire detected with low fuel level