

Vehicle Information

Land Rover 2006 Discovery (L319)

VIN: SALAE25476A386585

Diagnostics time: 2022/09/24 08:56

Mileage:

Path: Automatic selection > Diagnosis > Auto scan >

Status report

Status	DTC counts	System name
Fault	2	PCM (Powertrain Control Module)
Fault	2	TCM (Transmission Control Module)
Fault	1	RCM (Restraints Control Module)
Fault	3	IPC (Instrument Cluster Control Module)
Fault	4	PBM (Parking Brake Control Module)
Fault	1	TPM (Tire Pressure Monitor Module)
Pass	0	BCM (Body Control Module)
Fault	6	TCCM (Transfer Case Control Module)
Fault	2	ATCM (All Terrain Control Module)
Fault	1	RLM (Ride Level Control Module)
Pass	0	SASM (Steering Angle Sensor Module)
Fault	3	VDM (Vehicle Dynamics Control Module)
Pass	0	ACM (Audio Front Control Module)
Pass	0	HVAC (Heating Ventilation And Air Conditioning Control Module)
Pass	0	PAM (Parking Assist Control Module)
Pass	0	AAM (Audio Amplifier Module)
Fault	2	PCM (Powertrain Control Module)
DTC code	DTC status	DTC content
P0504-64	Intermittent	Brake switch A/B correlation.
P0504-29	Intermittent	Brake switch A/B correlation.
Fault	2	TCM (Transmission Control Module)
DTC code	DTC status	DTC content
U0416-86	Intermittent	Invalid data sent from vehicle dynamics control module.
U0122-87	Temporary	Lost communication with vehicle dynamics control module.
Fault	1	RCM (Restraints Control Module)
DTC code	DTC status	DTC content
U0073-88	Intermittent	Control module communication bus-off.
Fault	3	IPC (Instrument Cluster Control Module)
DTC code	DTC status	DTC content
U0001-88	Temporary	HS CAN communication bus
U0010-88	Temporary	MS CAN communication bus

U0127-87	Intermittent	Lost communication with TPM module.
Fault	4	PBM (Parking Brake Control Module)
DTC code	DTC status	DTC content
U0155-87	Intermittent	Lost communication with instrument cluster control module.
U0122-87	Intermittent	Lost communication with vehicle dynamics control module.
U0100-87	Intermittent	Lost communication with ECM/PCM A
U0101-87	Intermittent	Lost communication with Transmission Control Module (TCM)
Fault	1	TPM (Tire Pressure Monitor Module)
DTC code	DTC status	DTC content
C1A62-93	Intermittent	Right rear tire pressure sensor and transmitter assembly
Fault	6	TCCM (Transfer Case Control Module)
DTC code	DTC status	DTC content
U0073-88	Intermittent	Control module communication bus-off.
U0100-87	Intermittent	Lost communication with ECM/PCM A
U0128-87	Intermittent	Lost communication with parking brake control module
U0155-87	Intermittent	Lost communication with instrument cluster control module.
U0126-87	Intermittent	Lost communication with steering angle sensor module
U0122-87	Intermittent	Lost communication with vehicle dynamics control module.
Fault	2	ATCM (All Terrain Control Module)
DTC code	DTC status	DTC content
U0416-94	Temporary	Invalid data sent from vehicle dynamics control module.
U0421-94	Temporary	Invalid data sent from ride level control module.
Fault	1	RLM (Ride Level Control Module)
DTC code	DTC status	DTC content
U0416-86	Temporary	Invalid data sent from vehicle dynamics control module.
Fault	3	VDM (Vehicle Dynamics Control Module)
DTC code	DTC status	DTC content
C1A96-13	Intermittent	Brake Lamp Switch (BLS) circuit.
C1A00-88	Permanent	Control module
U0128-87	Permanent	Lost communication with parking brake control module