

Fault(s) List on SALAA254X5A300874

Stephen Sullivan <ssullivan@constructionanalysis.net>

Wed 5/8/2024 6:56 PM

To:GAP Team <gapteam@gap-diagnostic.com>

VIN SALAA254X5A300874

Model L319 - LR3 2005

Vehicle scanned on May 8, 2024 6:55:30 PM

IIDControl 4.2.6 Build 158 Android - IIDTool BT V4.0 B3926

Audio System

B1D79-01 - Microphone input - General failure information - general electrical failure (28)
(on 06-05-2024 08:11:41 at 99479 mi)

Body Control

B1A93-93 - Invalid roof position - Component failure - no operation (2B)
(on 05-05-2024 17:10:55 at 99475 mi)

B1A98-83 - Local interconnection network bus circuit 1 - Bus signal/message failure - value of signal protection calculation is incorrect (68)
(on 05-05-2024 17:13:41 at 99475 mi)

B1B02-28 - Low frequency coil - General signal failure - signal bias level is out of range/zero adjustment failure (2B)
(on 05-05-2024 17:13:36 at 99475 mi)

B1B69-16 - 12 volt supply circuit - General electrical failure - circuit voltage below threshold (2A)
(on 05-05-2024 17:13:41 at 99475 mi)

B1C26-3A - Pedal motor feedback circuit - Frequency modulation/pulse width modulation failure - incorrect, has too many pulses (2B)
(on 05-05-2024 17:10:56 at 99475 mi)

B1C32-13 - Steering column tilt solenoid - General electrical failure - circuit open (2B)
(on 05-05-2024 17:10:56 at 99475 mi)

B1C33-3A - Steering column tilt feedback signal - Frequency modulation/pulse width modulation failure - incorrect, has too many pulses (28)
(on 05-05-2024 14:55:38 at 99475 mi)

B1C34-13 - Steering column telescope solenoid - General electrical failure - circuit open (2B)
(on 05-05-2024 17:10:56 at 99475 mi)

B1C35-3A - Steering column telescope feedback signal - Frequency modulation/pulse width modulation failure - incorrect, has too many pulses (28)
(on 05-05-2024 14:55:38 at 99475 mi)

B1C57-14 - Passive start ignition relay coil circuit - General electrical failure - circuit short to ground or open (68)
(on 05-05-2024 14:55:38 at 99475 mi)

B1C82-14 - Headlamp washer relay coil circuit - General electrical failure - circuit short to ground or open (28)
(on 05-05-2024 17:12:58 at 99475 mi)

B1C96-13 - Alarm LED circuit - General electrical failure - circuit open (2B)
(on 08-05-2024 18:43:11 at 99475 mi)

B1D14-15 - Interior lamps 2 circuit - General electrical failure - circuit short to battery or open (2B)
(on 05-05-2024 17:33:41 at 99475 mi)

U0155-87 - LCD Gauge Communication Lost - Bus signal/message failure - missing a message (2A)
(on 05-05-2024 17:16:29 at 99475 mi)

Instrument Pack

U0100-87 - Lost communication with engine control module/powertrain control module 'A' - Bus signal/message failure - missing a message (28)
(on 14-12-2037 16:45:26 at 99479 mi)

Parking Brake

U0100-87 - Lost communication with engine control module/powertrain control module 'A' - Bus signal/message failure - missing a message (A8)

(on 05-05-2024 17:07:14 at 99479 mi)

Steering Angle

U0122-87 - Lost communication with vehicle dynamics control module - Bus signal/message failure - missing a message (28)

(on 05-05-2024 17:07:17 at 99479 mi)

Terrain Response

U0100-87 - Lost communication with engine control module/powertrain control module 'A' - Bus signal/message failure - missing a message (28)

(on 05-05-2024 17:10:20 at 99479 mi)

Transfer Case

U0100-87 - Lost communication with engine control module/powertrain control module 'A' - Bus signal/message failure - missing a message (28)

(on 05-05-2024 17:09:59 at 99479 mi)

U0155-87 - LCD Gauge Communication Lost - Bus signal/message failure - missing a message (28)

(on 05-05-2024 17:35:12 at 99479 mi)

U1A35-4A - VIN data - System internal failure - incorrect component installed (2B)

(on 05-05-2024 17:09:59 at 99479 mi)

Transmission

U0100-87 - Lost communication with engine control module/powertrain control module 'A' - Bus signal/message failure - missing a message (A8)

(on 05-05-2024 17:07:14 at 99479 mi)

U0155-87 - LCD Gauge Communication Lost - Bus signal/message failure - missing a message (69)

(on 05-05-2024 17:35:09 at 99479 mi)

Vehicle Dynamic

U0100-87 - Lost communication with engine control module/powertrain control module 'A' - Bus signal/message failure - missing a

message (08)

(on 05-05-2024 17:13:39 at 99479 mi)

U0424-68 - Invalid data received from heating, ventilation and air conditioning control module - Algorithm based failure - event information (08)

(on 05-05-2024 17:35:10 at 99479 mi)