

EXISTING SERVICES

Job	Quote
CHK.ENG.LIGHT ON CUST STATES CHECK ENGINE LIGHT ON	PENDING
ELEC BODY CUSTOMER STATES HIGH REV UPON START UP AND THEN GOES BACK T	PENDING
MULTI POINT INSPECT REQUEST PERFORM MULTI-POINT INSPECTION	INTERNAL
Existing Services Total	\$

SUGGESTED SERVICES

Job			Quote	
ENGINE LIGHT IMMEDIATE ATTENTION CUSTOMER STATES CHECK ENGINE LIGHT ON SCANNED VEHICLE FOR FAULTS FOUND FAULT CODES LEAN BANK1 AND 2. CHECKED PCV FOUND VACUUM LEAK			517.89	
Qty	Part Number	Part Description	Price	Ext Price
1.00	LR133579	SERVICE KIT - PC	63.71	63.71
Misc Code	Misc Description			Ext Price
EPA	WASTE DISPOSAL			12.00
			Labor 2.00 Hrs	410.00
			Parts	63.71
			Misc	12.00
			Tax	32.18
			Total	517.89



Jaguar Land Rover Marlboro

Job				Quote	
OIL LEAK				IMMEDIATE ATTENTION	
UPON INSPECTION TECH NOTED OIL LEAK				6,563.17	
FOUND OIL LEAK COMING FROM BOTH VALVE COVER GASKETS AND UPPER TIMING COVERS					
Qty	Part Number	Part Description	Price	Ext Price	
1.00	LR041869	GASKET - CAMSHAF	76.04	76.04	
3.00	LR014345	GASKET - SPARK P	42.28	126.84	
1.00	LR089050	GASKET - CAMSHAF	76.04	76.04	
3.00	LR011220	GASKET - SPARK P	42.28	126.84	
2.00	LR041681	GASKET - INTAKE	27.30	54.60	
1.00	LR041680	GASKET - INTAKE	86.19	86.19	
6.00	LR037089	KIT - INJECTOR	54.26	325.56	
1.00	LR048165	GASKET - THROTTL	51.62	51.62	
1.00	STC50550	SEALER - ADHESIV	34.54	34.54	
1.00	LRN2279	FLUID - COOLING	60.10	60.10	
Misc Code	Misc Description			Ext Price	
EPA	WASTE DISPOSAL			12.00	
			Labor	25.00 Hrs	5,125.00
			Parts		1018.37
			Misc		12.00
			Tax		407.80
			Total		6563.17
Suggested Services Total				\$	7081.06

Total Estimate \$ 7068.27