

## Events by distance



VIN: SALAK2V67EA727394  
 Model: Land Rover L319 Land Rover LR3\LR4  
 Session creation: Wed 30-Aug-2023 13:09  
 Session printed: Wed 30-Aug-2023 13:12  
 Current odometer: 134,450km



DTC	ECU	Distance	Time	Description	Status	Options	Relevance
<b>134,401km - Event 8</b>							
P0300-00	PCM	134,401km	8/30/23 11:32 AM	Random Misfire Detected - No sub type information			100%
P0302-00	PCM	134,401km	8/30/23 11:32 AM	Cylinder 2 Misfire Detected - No sub type information			100%
P0301-00	PCM	134,401km	8/30/23 11:32 AM	Cylinder 1 Misfire Detected - No sub type information			100%
<b>134,268km - Event 7</b>							
P0305-00	PCM	134,268km	8/30/23 8:41 AM	Cylinder 5 Misfire Detected - No sub type information			100%
P0306-00	PCM	134,268km	8/30/23 8:41 AM	Cylinder 6 Misfire Detected - No sub type information			100%
<b>134,261km - Event 6</b>							
P2189-00	PCM	134,261km	8/30/23 8:05 AM	System Too Lean at Idle - Bank 2 - No sub type information			19%
P2187-00	PCM	134,261km	8/30/23 8:05 AM	System Too Lean at Idle - Bank 1 - No sub type information			19%
<b>129,870km - Event 5</b>							
C1A60-93	BCM	129,870km	8/10/23 10:29 PM	Left Rear Tire Pressure Sensor and Transmitter Assembly - No operation			
<b>129,478km - Event 4</b>							
C1A58-93	BCM	129,478km	8/9/23 4:26 AM	Right Front Tire Pressure Sensor and Transmitter Assembly - No operation			
<b>129,432km - Event 3</b>							
C1A56-93	BCM	129,432km	8/8/23 11:01 PM	Left Front Tire Pressure Sensor and Transmitter Assembly - No operation			
C1A62-93	BCM	129,432km	8/8/23 11:01 PM	Right Rear Tire Pressure Sensor and Transmitter Assembly - No operation			
<b>129,115km - Event 2</b>							
C1D21-05	BCM	129,115km	8/7/23 6:05 PM	Wheel Module - System programming failures			
<b>129,086km - Event 1</b>							
U0102-00	RLM	129,086km	8/7/23 1:19 PM	Lost Communication with Transfer Case Control Module - No sub type information			
U0241-00	BCM	129,086km	8/7/23 1:19 PM	Lost Communication With Headlamp Control Module "A" - No sub type information			
U0102-00	IPC	129,086km	8/7/23 1:27 PM	Lost Communication with Transfer Case Control Module - No sub type information			
B13C5-92	GWM	129,086km	8/7/23 1:27 PM	Secondary Battery - Performance or incorrect operation			
U0447-00	PCM	129,086km	8/7/23 1:27 PM	Invalid Data Received From Gateway "A" - No sub type information			
<b>Unknown Events</b>							
P0304-00	PCM	-----km	--/-- --:--	Cylinder 4 Misfire Detected - No sub type information			100%
U0146-00	PCM	-----km	--/-- --:--	Lost Communication With Gateway "A" - No sub type information			