



Land Rover : Discovery : 2017-20 : with Air Spring Suspension ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE / REG. #	MILEAGE IN / OUT	TAG	
BLACK	20	LAND ROVER DISCOVERY	SALRU2RV0L2428156		18833/18834	TT001	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
15AUG20 DD			WAIT 17DEC21		189.00	CASH	17DEC21

R.O. OPENED: 08:21 17DEC21
 READY: 11:15 17DEC21
 OPTIONS: SOLD-STK:R1533 DLR:3904
 ENG:3.0 Liter S/C TRN:8 Speed Automatic 1)LR
 OWNER CARE 2)TERM 36 MONTHS 3)PROGRAM TH (More...)

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL
 A C/S: C/S DRIVERSIDE FRONT TIRE IS READING LOW PSI AFTER AIR WAS PUT
 IN TIRE. HEARS A CLUNKING SOUND WHEN TURNING LEFT OR RIGHT
 74 TIRE OR WHEEL PERFORMANCE CONCERN (SHAKING,
 PULLING, ROAD NOISE, ETC.)
 3101 CPL 0.00 0.00
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
18833 heard slight noise form transfer box while cornering. will
new double flush and t box update. updated t box software and
performed double flush

B MULTI POINT INSPECTION
 99P CUSTOMER REQUEST MULTI-POINT INSPECTION OF
 VEHICLE.
 3101 CPL 0.00 0.00
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

C** PERFORM COMPUTERIZED FOUR WHEEL ALIGNMENT - SET TO FACTORY SPEC'S.
 CAUSE: front tire wear and steering off center
 4WA PERFORM COMPUTERIZED FOUR WHEEL ALIGNMENT
 SET TO FACTORY SPEC'S.
 3101 CPL 249.95 249.95
 PARTS: 0.00 LABOR: 249.95 OTHER: 0.00 TOTAL LINE C: 249.95
18833 completed 4wa

D** MOUNT AND ROAD FORCE BALANCE TWO TIRES
 CAUSE: both front tires have no tread
 M2 MOUNT AND ROAD FORCE BALANCE TWO TIRES
 3101 CPL 100.00 100.00
 2 3432400 SCORPION ZERO A/ 314.00 275.00 550.00
 PARTS: 550.00 LABOR: 100.00 OTHER: 0.00 TOTAL LINE D: 650.00
18833 replaced 2 front tires

E** nail in rr tire. repair
 TR PERFORM TIRE LEAK REPAIR

WARRANTY DISCLAIMER: ALL PARTS AND REPAIRS ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS IS. THE DEALERSHIP EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, MERCHANTABILITY AND FITNESS FOR ANY PARTICULAR PURPOSE. THE MANUFACTURER OR SUPPLIER OF ANY PARTS OR PRODUCTS IS NOT BEING LIABLY FOR PERFORMANCE OR DAMAGES FOR LOSS OF USE, INCIDENTAL DAMAGES, OR REPAIRS AT THE ORIGINAL PARTS DISTRIBUTOR. BY SIGNING BELOW, YOU ACKNOWLEDGE AND AGREE TO PERFORM THE SERVICES/REPAIRS (INCLUDING INSPECTION) AND RETURN TO YOU IN EXCHANGE FOR THE ORIGINAL PARTS AND REPAIRS.	IMPORTANT You may receive a customer satisfaction survey and/or phone call from Jaguar Land Rover North America in the near future. If for any reason you cannot grade us an OUTSTANDING rating, please contact our Service Department. THANK YOU Jaguar Land Rover Main Line 610-520-2000	*SHOP SUPPLY / HAZ WASTE A shop supply charge of \$3.50 has been assessed.	DESCRIPTION	TOTALS
		LABOR AMOUNT		
		PARTS AMOUNT		
		GAS, OIL, LUBE		
		SUBLET AMOUNT		
		MISC. CHARGES *		
TOTAL CHARGES				
LESS INSURANCE				
SALES TAX				
DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT	