

MAINTENANCE SERVICE REMINDER

NOTE: To determine the appropriate reset procedure, refer to **MAINTENANCE SERVICE REMINDER RESET INDEX**. Only vehicles listed in this index have a Service Interval Indicator reset.

MAINTENANCE SERVICE REMINDER RESET INDEX

Model & Year	Reset Procedure
Discovery	
1999-04	Maintenance Service Reminder Reset - Procedure 01
2017-19	Maintenance Service Reminder Reset - Procedure 08
Discovery Sport	
2015-19	Maintenance Service Reminder Reset - Procedure 08
Freelander	
2002-05	Maintenance Service Reminder Reset - Procedure 04
LR2	
2008-11	Maintenance Service Reminder Reset - Procedure 03
2012-15	Maintenance Service Reminder Reset - Procedure 07
LR3	
2005-09	Maintenance Service Reminder Reset - Procedure 05
LR4	
2010-13	Maintenance Service Reminder Reset - Procedure 05
2014-16	Maintenance Service Reminder Reset - Procedure 08
Range Rover	
2002-05	Maintenance Service Reminder Reset - Procedure 02
2006-09	Maintenance Service Reminder Reset - Procedure 06
2010-12	Maintenance Service Reminder Reset - Procedure 05
2013-19	Maintenance Service Reminder Reset - Procedure 08
Range Rover Evoque	
2012-13	Maintenance Service Reminder Reset - Procedure 07
<hr/>	
Model & Year	Reset Procedure
2014-19	Maintenance Service Reminder Reset - Procedure 08
Range Rover Sport	
2006-09	Maintenance Service Reminder Reset - Procedure 04
2010-13	Maintenance Service Reminder Reset - Procedure 05
2014-19	Maintenance Service Reminder Reset - Procedure 08

MAINTENANCE SERVICE REMINDER RESET - PROCEDURE 08

NOTE: Make sure Land Rover approved diagnostic equipment is not connected to the vehicle.

1. Set the ignition to the ON position.
2. Open the hood.
3. Open the drivers door.
4. Fully depress both the accelerator and brake pedals and hold for 10 seconds.

NOTE: A service resetting message will appear on the instrument cluster.

5. Set the ignition to the OFF position.
6. Set the ignition to the ON position and check the message has been cleared.
7. If the message remains, repeat the process.