


Description: *Sensor-Knock-LH bank*

Location: *Lower rear of engine - LH side*

Cav	Col	Cct
1	KW	ALL
2	B	ALL



YPC110130

Colour: *BLACK*

Gender: *Female*