


Part No. 8380698
 Colour: BLACK
 Gender: F
 Type: MICRO TIMER 3
 No. of Ways: 16WY



Description: Diagnostic socket
 Location: Behind driver side of fascia

Connector Details

YPL103470	
Cavities 1,4,5,7-9,16	
0.20 - 0.50 CSA	
1	VDK500010 INSTRUCTION; REPAIR KIT
1	VDK500120 INSTRUCTION; EXTRACT TOOL
1	YMI001070 PRE-TERMINATED LEAD
1	YF0000100 IDENTIS (SMALL)
1	YRV000040 SPLICE (RED, CSA; 0.25-1.6)
1	YRW000390 WIRE STRIPPER
1	YRW500010 APPLICATOR
1	YRW500110 EXTRACT TOOL
[VUB500270]	

Service Repair Kits

CAV	TERMINAL	CSA	COL	CCT	DESTN
1	YPL103470	0.5	GW	ALL	C0587-13
4	YPL103470	0.5	NB	ALL	C0287-0
5	YPL103470	0.5	NB	ALL	C0287-0
7	YPL103470	0.35	WPY	573	SJ X442-

Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
7	YPL103470	0.35	WPY	58	C0331-32
8	YPL103470	0.35	WP	ALL	SJ X189-
9	YPL103470	0.35	B	ALL	C0331-17
16	YPL103470	0.5	RUY	ALL	C0586-26