


Cav	Col	Cct
1	KB	ALL
2	B	ALL

Description: *Sensor-Knock-RH bank*
Location: *Lower rear of engine - RH side*



YPC110130

Colour: *BLACK*
Gender: *Female*