

# Smog Check Vehicle Inspection Report (VIR)

## Vehicle Information

Test Date/Time: 07/23/2021 @ 10:02 AM

Model Year: 2011	Vehicle Make: LAND ROVER	Vehicle Model: LR4 HSE
VIN (scanned from vehicle): SALAG2D40BA588674		
VIN (manually entered or from DMV document): SALAG2D40BA588674		
License Plate: 8NVT027	License State: CA	Fuel Type: Gasoline
Certification Type: California	Odometer: 103784	GVWR: 6,001 - 10,000

## **Overall Test Result**

**PASS**

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: SE073563C

DMV ID Number: 7619E868S864

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

## Visual Inspection Result Information

<u>Result</u>	<u>Inspection Category</u>	<u>Result</u>	<u>Inspection Category</u>
NOT APPLICABLE	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOT APPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOT APPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

## Emission Control Systems Functional Check Results

<u>Result</u>		<u>Result</u>	
PASS	Liquid Fuel Leak Check	PASS	OBDII
PASS	Smoke Check		

## Smog Check Inspection Station Information

Station ID: RC283973	Inspector Name/ID: TRAN, BINH/EO638653
STAR SMOG & ALIGNMENT HAUS	Software Version/OIS ID: 21.1.1227.0/CV012816
17510 WOODRUFF AVE	
BELLFLOWER, CA 90706	
(562) 888-0186	

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

7/23/21  
Date

[Signature]  
Inspector's Signature